Peddinghaus
Paul Ferdinand Peddinghaus GmbH

Preparing for transport:

Please place your machine on a pallet as shown in the photo. Bolt the machine to the pallet or secure it with a steel strap or a belt as shown in the photo.



As the machines are top-heavy, please attach the following paper sign to both sides of the upper part of the machine.

